

Basik Air Concept
559 Chemin des Salles
83300 Draguignan
tel: 04 94 99 12 36
fax: 04 94 39 89 37
E-mail: basik.fr@free.fr

TECHNICAL ADVISORY

N° AV070716
Date 16/07/2007
Page 1/1

EQUIPEMENTS CONCERNED

Advance Tandem system T1 and T2

Equipement concerned: Advance Tandem T1 and T2

Subject It is request to all Advance tandem user to verify the white locking loop of the cutaway system on the main risers. Grommets must be check as well.

Reasons: Potential risk of white loop damage and even failure because of friction between the loop and the riser grommet.

Application: Immediat and equipment check every day

Works: Visual control of the locking loop. None of the fiber must be damaged (photos). Verify the riser grommet as shown on the photos by checking de grommet edge. If sharp edge, check the evolution of the white loop and polish the grommet edge with a Dremel kind tool.

Jérôme Bunker



Ludovic Chevé



